

Bill of materials for “Polymerization process: curing time and heating”:

Necessary equipment:

- Laboratory drying oven or hotplate (which reach 65°C): 20€

<https://www.amazon.com/Cusimax-Electric-Hot-Plate-Cooking/dp/B06XD3JZ95>

- A timer
- Polymerization chamber: the place where you do want the PDMS to be cured.

You could find the designs to laser cutter our chambers in our GitHub. 10 units will cost 60€ in a normal laser cutter business. Check the assemblies section for further information

You could also use Petri dishes.

**Total:** 80€